

United States of America  
Department of Transportation -- Federal Aviation Administration

# Supplemental Type Certificate

IMPORT

*Number* SA01342NY

*This certificate is issued to* Insight Instrument Corporation  
Box 122  
Ft. Erie, ON L2A 5M6  
Canada

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number :* A10SW, A2PC

*Make :* Mitsubishi

*Model :* B (MU-2B), D (MU-2B-10), DP (MU-2B-15), F (MU-2B-20),  
K (MU-2B-25), M (MU-2B-26), P (MU-2B-26A), Solitaire  
(MU-2B-40)

*Description of Type Design Change:*

Installation of the MU-2 Torque Knee Spring in accordance with Insight Instrument Corp. Installation Procedure Document No. 012008, dated January 20, 2001.

*Limitations and Conditions:*

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* February 20, 2001

*Date reissued :*

*Date of issuance :* April 20, 2001

*Date amended :*



*By direction of the Administrator*

*Vito A. Pulera*  
for \_\_\_\_\_  
(Signature)

Vito A. Pulera  
Manager  
New York Aircraft Certification Office

\_\_\_\_\_  
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.